ABC Radon Testing Company

123 Main Street
Harrisburg, PA 17101
(301) 555-5555
info@abcradon.org

Radon Test Report

June 14, 2018
Batch #: 061418-2

Customer:

Sample Customer
999 Radium Ln.
Annapolis MD 21401

Test Site:

Sample Customer
999 Radium Ln.
Annapolis MD 21401

A Rad Elec Recon Continuous Radon Monitor was used for the short-term radon screening measurement that was conducted at the above referenced test site by: ABC Radon Testing Company

The Results are as follows:

Serial No.	Type	Location	Test Start Date		Test End Date		Test Results
207	CRM	First Floor	04-May-2018	02:45 PM	07-May-2018	09:47 AM	3.6

Average Radon Concentration in: First Floor **3.6 pCi/L**

Deployed By: Joe Tech 1234567890
Retrieved By: Joe Tech 1234567890
Analyzed By: Joe Tech 1234567890

Conditions: Requirements for Closed-Building Met
Tampering: None Observed
Weather: No Abnormal Weather Conditions
Mitigation: No System Installed

Radon Health Risk Information

Radon is the second leading cause of lung cancer after smoking. The U.S. Environmental Protection Agency (EPA) and the Surgeon General strongly recommend that further action be taken when a home's radon test results are 4.0 pCi/L or greater. The national average indoor radon level is about 1.3 pCi/L. The higher the home's radon level, the greater the health risk to you and your family. Reducing your radon levels can be done easily, effectively and fairly inexpensively. Even homes with very high radon levels can be reduced below 4.0 pCi/L. Please refer to the EPA website at www.epa.gov/radon for further information to assist you in evaluating your test results or deciding if further action is needed.

Signature: Joe Tech **Date:** 14-Jun-2018

ABC Radon Testing Company

123 Main Street
Harrisburg, PA 17101
(301) 555-5555
info@abcradon.org

Radon Test Report

June 14, 2018
Batch #: 061418-2


Customer:

Sample Customer
999 Radium Ln.
Annapolis MD 21401


Test Site:

Sample Customer
999 Radium Ln.
Annapolis MD 21401


Graphical Results for: Rad Elec Recon 207



Temperature & Tilts



Humidity & Pressure



ABC Radon Testing Company

123 Main Street
Harrisburg, PA 17101
(301) 555-5555
info@abcradon.org

Radon Test Report

June 14, 2018
Batch #: 061418-2

Customer:

Sample Customer
999 Radium Ln.
Annapolis MD 21401

Test Site:

Sample Customer
999 Radium Ln.
Annapolis MD 21401

Hourly Detailed Report for: Rad Elec Recon 207

Record #	Date/Time	pCi/L	Fahrenheit (°F)	Pressure (inHg)	Humidity (%)	Tilts
1	04-May-2018 15:45	1.3	76	29.0	40	24
2	04-May-2018 16:45	1.9	75	29.0	40	129
3	04-May-2018 17:45	2.2	75	29.0	40	9
4	04-May-2018 18:45	1.8	74	29.0	40	0
5	04-May-2018 19:45	3.0	75	29.0	40	0
6	04-May-2018 20:45	1.8	76	29.0	40	0
7	04-May-2018 21:45	1.7	76	29.0	39	153
8	04-May-2018 22:45	3.4	77	29.1	39	174
9	04-May-2018 23:45	2.8	78	29.1	38	43
10	05-May-2018 00:45	3.6	78	29.1	38	62
11	05-May-2018 01:45	2.7	77	29.1	37	183
12	05-May-2018 02:45	3.4	75	29.1	37	108
13	05-May-2018 03:45	3.7	73	29.1	37	0
14	05-May-2018 04:45	3.1	72	29.2	38	0
15	05-May-2018 05:45	3.8	72	29.2	39	0
16	05-May-2018 06:45	3.0	72	29.2	39	0
17	05-May-2018 07:45	2.5	72	29.2	39	0
18	05-May-2018 08:45	3.8	72	29.2	39	0
19	05-May-2018 09:45	4.3	72	29.2	39	83
20	05-May-2018 10:45	3.8	73	29.2	40	262
21	05-May-2018 11:45	4.2	73	29.2	39	73
22	05-May-2018 12:45	4.3	74	29.2	39	0
23	05-May-2018 13:45	5.0	73	29.2	39	0
24	05-May-2018 14:45	3.6	73	29.2	39	0
25	05-May-2018 15:45	3.3	73	29.2	39	3
26	05-May-2018 16:45	3.8	73	29.2	40	0
27	05-May-2018 17:45	4.3	73	29.2	40	0
28	05-May-2018 18:45	3.7	73	29.2	40	0
29	05-May-2018 19:45	4.0	72	29.2	40	0
30	05-May-2018 20:45	3.8	72	29.2	40	0
31	05-May-2018 21:45	5.0	72	29.2	40	0
32	05-May-2018 22:45	4.2	71	29.2	40	0
33	05-May-2018 23:45	3.9	71	29.2	41	3
34	06-May-2018 00:45	5.3	70	29.2	41	83
35	06-May-2018 01:45	4.5	72	29.2	40	109
36	06-May-2018 02:45	4.9	73	29.1	40	120
37	06-May-2018 03:45	3.5	73	29.1	40	111
38	06-May-2018 04:45	3.7	72	29.1	40	0
39	06-May-2018 05:45	3.3	71	29.1	40	0
40	06-May-2018 06:45	4.8	69	29.1	40	0
41	06-May-2018 07:45	2.5	68	29.1	41	0
42	06-May-2018 08:45	3.2	68	29.1	41	0

ABC Radon Testing Company

123 Main Street
Harrisburg, PA 17101
(301) 555-5555
info@abcradon.org

Radon Test Report

June 14, 2018
Batch #: 061418-2

Customer:

Sample Customer
999 Radium Ln.
Annapolis MD 21401

Test Site:

Sample Customer
999 Radium Ln.
Annapolis MD 21401

Record #	Date/Time	pCi/L	Fahrenheit (°F)	Pressure (inHg)	Humidity (%)	Tilts
43	06-May-2018 09:45	3.4	67	29.1	41	0
44	06-May-2018 10:45	3.5	67	29.0	42	9
45	06-May-2018 11:45	3.3	67	29.0	42	0
46	06-May-2018 12:45	2.6	67	29.0	43	24
47	06-May-2018 13:45	3.9	67	29.0	43	0
48	06-May-2018 14:45	3.7	67	29.0	43	0
49	06-May-2018 15:45	3.8	67	29.0	43	0
50	06-May-2018 16:45	4.2	67	29.0	44	0
51	06-May-2018 17:45	2.9	67	29.0	44	0
52	06-May-2018 18:45	3.4	67	29.0	44	0
53	06-May-2018 19:45	3.3	67	29.0	45	0
54	06-May-2018 20:45	3.6	67	29.0	45	0
55	06-May-2018 21:45	3.8	67	29.1	45	4
56	06-May-2018 22:45	3.1	67	29.1	45	0
57	06-May-2018 23:45	3.8	67	29.1	45	203
58	07-May-2018 00:45	3.1	69	29.1	45	131
59	07-May-2018 01:45	4.7	70	29.1	44	112
60	07-May-2018 02:45	3.6	69	29.1	44	0
61	07-May-2018 03:45	4.0	67	29.1	44	0
62	07-May-2018 04:45	2.6	67	29.1	44	0
63	07-May-2018 05:45	4.5	66	29.1	45	3
64	07-May-2018 06:45	3.4	65	29.1	45	0
65	07-May-2018 07:45	3.0	65	29.1	45	0
66	07-May-2018 08:45	4.7	65	29.2	45	0
67	07-May-2018 09:45	3.8	64	29.2	45	110